
From: Sannan, Bill (Houston)
Sent: Sunday, November 01, 2009 7:35 PM
To: Wright, Mike (Houston); Adamson, Keelan (Houston); Rose, Adrian (Houston); Birmingham, Hank (Houston); Bobillier, Arnaud (Geneva); Bonno, Terry (Geneva); Boone, John (Houston); Canducci, Jerry (Houston); Cleaver, Marc (Houston); Hall, Eric (Houston); Hand, Steve (Houston); Johnson, Tony (Houston); McMahan, Larry (Houston); Legrand, Michel; McAllister, Kathleen (Houston); Moore, Jimmy (Houston); Ness, Chris (Houston); Guichenev, Patrick (Geneva); Tranter, Paul (Geneva); Smith, Pharr (Houston); Pirtle, Donnie (Houston); Reudelhuber, Dan (Houston); Richards, Jess (Houston); Saltiel, Rob (Houston); Newman, Steven (Geneva); Trahan, Buddy (Houston); Watson, Simon (Houston); Winslow, Daun (Houston)
Subject: Marianas Shear Rams - Operations Abnormality Notification
Attachments: MAR-Shear Rams on Yellow Pod Failure.doc; image003.jpg; image004.gif; image005.gif

The Marianas is pulling their BOP stack after running and cementing 18" casing. The shear rams cannot be functioned from the Yellow pod. Additionally, the lower annular will not close and the upper annular has been stripped through during a well control event.

Regards,

Bill Sannan

-----Original Message-----

From: Hockaday, Wilton (Houston)
Sent: Sunday, November 01, 2009 1:09 PM
To: DL-NAM OP_ABNORMALITY
Cc: Winslow, Daun (Houston)
Subject: Abnormality Report

All,

Initial report regarding Yellow Pod failure on the Marianas and subsequent BOP stack pull.

RIGCentral Home <<http://www.rigcentral.com/>>

Wilton N. Hockaday

Rig Manager - Asset

Marianas - North America Region

[REDACTED] (Office)

[REDACTED] (Cell)

[REDACTED]

From: Watson, Simon (Houston)
Sent: Sunday, November 01, 2009 10:34 PM
To: Sannan, Bill (Houston); Pirtle, Donnie (Houston)
Subject: RE: Marianas Shear Rams - Operations Abnormality Notification
Attachments: image001.jpg; image002.gif; image003.gif

Bill,

The annular we changed last time, was it the lower or the upper. We had an issue earlier in the year where an annular that had just been overhauled failed upon installation. Is there any concern that the annular we have just changed was questionable

Thanks

Simon

From: Sannan, Bill (Houston)
Sent: Sunday, November 01, 2009 1:35 PM
To: Wright, Mike (Houston); Adamson, Keelan (Houston); Rose, Adrian (Houston); Birmingham, Hank (Houston); Bobillier, Arnaud (Geneva); Bonno, Terry (Geneva); Boone, John (Houston); Canducci, Jerry (Houston); Cleaver, Marc (Houston); Hall, Eric (Houston); Hand, Steve (Houston); Johnson, Tony (Houston); McMahan, Larry (Houston); Legrand, Michel; McAllister, Kathleen (Houston); Moore, Jimmy (Houston); Ness, Chris (Houston); Guicheney, Patrick (Geneva); Tranter, Paul (Geneva); Smith, Pharr (Houston); Pirtle, Donnie (Houston); Reudelhuber, Dan (Houston); Richards, Jess (Houston); Saltiel, Rob (Houston); Newman, Steven (Geneva); Trahan, Buddy (Houston); Watson, Simon (Houston); Winslow, Daun (Houston)
Subject: Marianas Shear Rams - Operations Abnormality Notification

The Marianas is pulling their BOP stack after running and cementing 18" casing.. The shear rams cannot be functioned from the Yellow pod. Additionally, the lower annular will not close and the upper annular has been stripped through during a well control event.

Regards,

Bill Sannan

-----Original Message-----

From: Hockaday, Wilton (Houston)
Sent: Sunday, November 01, 2009 1:09 PM
To: DL-NAM OP_ABNORMALITY